


ADA ÖLÇÜ KROKİSİ

İLİ	: HATAY
İLÇESİ	: ARSUZ
MAH./KÖY	: KARAHÜSEYİNLİ
ADA/PARSEL NO:	2/1,2



KOORDİNAT ÖZET

Nokta No	Deprem Öncesi		Deformasyon		Nokta No	Deprem Öncesi		MK
	Y	X	DY	DX		Y	X	
110	508933.93	4045760.88	0.37	0.23	110	508933.56	4045760.65	0.09
111	508938.70	4045762.23	0.37	0.23	111	508938.33	4045762.00	0.09
112	508997.64	4045724.29	0.37	0.23	112	508997.27	4045724.06	0.09
113	508998.78	4045718.74	0.37	0.23	113	508998.41	4045718.51	0.09
114	508959.87	4045661.99	0.37	0.23	114	508959.50	4045661.76	0.09
115	508932.67	4045622.34	0.37	0.23	115	508932.30	4045622.11	0.09
116	508925.47	4045621.33	0.37	0.23	116	508925.10	4045621.10	0.09
117	508887.48	4045654.68	0.37	0.23	117	508887.11	4045654.45	0.09
118	508886.19	4045660.93	0.37	0.23	118	508885.82	4045660.70	0.09
119	508903.91	4045698.02	0.37	0.23	119	508903.54	4045697.79	0.09

DÜZENLEYEN		UYGUNDUR BELEDİYE/ÖZEL İDARE	
Adı Soyadı	Tarih	KONTROL EDEN	ONAYLAYAN

SUBHAN ÖZAY
 DENETİM DANIŞMANLIK
 VE MÜHÜRLEME LTD. ŞTİ.
 No:6 K:3 D:13-14
 5 Temmuz 2014 No:45 - İSKENDERUN
 Tel:03261 611 046 5020
 Akdeniz YOL 611 046 5020